



Industrial cactus drilling rig hit by tornado supplier

Did Cactus rig 117 withstand an F5 tornado?

At a cost of approximately \$500,000, Cactus anchored its rig change houses to withstand an F5 tornado. On 24 May 2011, Cactus Rig 117, operating near Calumet, Okla., suffered a direct hit by an F5 tornado that resulted in an estimated \$14 million in damage. An F5 tornado damaged Cactus Rig 117 after hitting the site on 24 May 2011.

Does cactus drilling have a tornado rig?

Cactus Drilling has nearly 40 rigs operating in Oklahoma, a state that suffers an average of 52 tornadoes a year. In 2007, a tornado in the state blew away a trailer house, killing a company man and injuring another employee.

Did a tornado hit a cactus 117 oil rig?

As per the Wikipedia article - "According to the National Weather Service, the tornado is believed to have peaked in intensity just after crossing I-40. There, the tornado struck the Cactus 117 oil drilling rig site at EF5 intensity, completely destroying it.

What happened at Cactus drilling?

In 2007, a tornado in the state blew away a trailer house, killing a company man and injuring another employee. Although neither worked for Cactus, the event gave Kathy Willingham, vice president of human resources and HSE for Cactus Drilling, the idea to prepare her company for tornado emergencies.

Did a cactus drilling investment save the lives of 12 men?

Kenny Baker, drilling superintendent for Cactus Drilling, shared a story at the IADC HSE&T Conference on 7 February in Houston on how a worthwhile investment saved the lives of 12 men during a tornado emergency in 2011. In the drilling business, there's nothing like being prepared.

What happened at Cactus 117 oil rig near Calumet?

An image taken by Kenny Baker showing what was left of the Cactus 117 oil rig near Calumet. A photo taken and provided by Jim LaDue, showing a mangled Chevrolet Avalanche that was thrown 780 yards near Piedmont. There are some figures regarding this tornado that may never be known.

This past May Oklahoma was hit by a string of tornadoes during a six day period, creating life-threatening conditions compounded by major flooding. Carl spent his days off of ...

Floyd said he didn't know the extent of the workers' injuries at the rig owned by Cactus Drilling. Emergency workers also contained a gas leak caused by damage to the plant, and damage ...

At least three were injured after a tornado hit a natural gas drilling rig in northern Texas on Wednesday



Industrial cactus drilling rig hit by tornado supplier

evening. At around 5:20 p.m. local time, the tornad...

A BOE contributor sent pictures of Cactus Rig 117, which was destroyed by a tornado on May 24, 2011, near Calumet, Oklahoma. The F5 ...

He is currently a volunteer for Grady County Emergency Management and also a member of the Grady County Community Emergency Response Team (CERT). This past May ...

Drill rig hit by tornado 05-26-2011, 12:57 PM Cactus 117 This happened yesterday, 5/24/2011, close to Calumet, OK- Pictures were taken by an SLB employee who was there - ...

The issue was the context; to put it bluntly, this was among the most violent tornadoes ever seen in modern times. The feats were numerous, varied, nearly beyond ...

A massive tornado flattened Cactus Drilling Company's #117 rig in Canadian County, Oklahoma but a tornado safety system saved the lives of the 11 crew, who weathered ...

Learn more about how Cactus Drilling utilizes the latest technology to make every operation safe and efficient for the benefit of all involved.

Rig Fleet Our high-spec, fit-for-purpose rigs are equipped with the technology, capacities and capabilities required to tackle today's most complex drilling ...

At a cost of approximately \$500,000, Cactus anchored its rig change houses to withstand an F5 tornado. On 24 May 2011, Cactus Rig 117, operating near ...

One cable broke and the container was dented, but all twelve workers survived without serious injury. [17]: 2[11]: 6 The move to tie down change houses for tornado shelters at Cactus drilling ...

Anyways, here's some absolutely incredible damage photos from the Cactus 117 Oil Rig where the tornado likely hit maximum intensity. This is easily some of the most violent and ...

Today, the contractor has 35 Rocket Rigs in its fleet. In 2010, Mr Baker was promoted to drilling superintendent, fulfilling the goal he'd set for ...

This is the first portion of a two-part series focusing on the Calumet-El Reno-Piedmont-Guthrie, OK, tornado of May 24, 2011. The summary covers the track from its ...

A drilling rig is a type of construction equipment used to make holes in the earth's surface. They can vary considerably in size: they can be massive structures or light enough to be moved ...



Industrial cactus drilling rig hit by tornado supplier

Cactus 117I got info/pics about this rig, damage, crew and where they were this morning from our safety guy. Pretty wild. "The rig was originally rigged up with the V-Door to ...

Cactus Rig 117 Canadian County, Oklahoma. Tornado Aftermath. Picture courtesy Derrick Brown. Link to Story* May 24, 2011 Injuries reported when storm hits Oklahoma oil rig ...

Oklahoma City-based Cactus Drilling Co. LLC credits its reinforced safe room for helping 13 employees and contractors survive a direct ...

The issue was the context; to put it bluntly, this was among the most violent tornadoes ever seen in modern times. The feats were numerous, ...

Jul 20, 2021 - Forwarded from one of our service techs: This happened yesterday, 5/24/2011, close to Calumet, OK- Pictures were taken by an SLB employee who was there - An F5 ...

EL RENO -- An El Reno official says 20 workers at an oil and gas rig were hurt when a possible tornado moved through the area. Community Services Director Terry Floyd also said Tuesday ...

One cable broke and the container was dented, but all twelve workers survived without serious injury. [17]: 2 [11]: 6 The move to tie down change houses for ...

No one was injured when the Cimarex-operated rig near the Devon plant was hit by Tuesday's tornado, said Steve Bell, the company's senior vice president. He said the rig, ...

EL RENO -- An El Reno official says 20 workers at an oil and gas rig were hurt when a possible tornado moved through the area. Community ...

The original shelter was designed after a tornado hit a Texas location in 2009. Since most of the company's Oklahoma and Texas rigs were in the tornado belt, Cactus believed something ...



Industrial cactus drilling rig hit by tornado supplier

Contact us for free full report

Web: <https://www.mwg-dobczyce.pl/contact-us/>